

## General Information

Client	PQC
Vessel	PQC VESSEL
Voyage	001 SR
Location	Bremerhaven
Survey	Special Report
Destination	Galveston/USA
Date	01.09.22



AIAG - SURVEY - CODE

## Summary

Total units	<b>1</b>
Inspected	1
Not inspected	0
Damaged units	<b>0</b>
%-Quote	0.0 %

## Damages

## Comment

Survey and weather conditions: Cloudy



V2.6

[www.port-quality-control.com](http://www.port-quality-control.com)

**CATERPILLAR**

XXXXXXXXXXXXC02022      CATERPILLAR      ACCESSORY PART      SR-DEBRV

New Cargo      None      None      TRS 0      None



V2.6

[www.port-quality-control.com](http://www.port-quality-control.com)